


RETIREMENT VILLAGE SAFETY

ARE YOUR RESIDENCE & STAFF SAFE FROM SLIPPERY SURFACES ?

In a split second a slip can cause major damage to head, back or limbs



This tiled area was very slippery. It was treated with AS-B Anti-Slip, now it offers greater slip resistance when wet.



The vinyl floor in this accessibility bathroom is much safer for both the resident and care giver following treatment with Grip Anti-Slip.

Wet Areas Definitely Pose Unseen Threats To The Elderly

Protect Them Before That Accident Occurs



The wooden ramp on the left was very dangerous when wet, the application of Little Grippas solved the problem.



These stairs caused concerns over safety issues. Not only were they slippery when wet, but in poor light there was also a lack of step edge definition.

Our stair nosings overcame both problems

For a **FREE, NO OBLIGATION** slip meter test, advice or quotation please contact your local licensed applicator on the number below. We have solutions for Tiles, Wooden Decks, Ramps & Steps, Concrete, Vinyl, Pool Surrounds, Baths & Showers.

Free Phone : 0800 251 563

or please visit www.anti-slip.co.nz for more ideas.